


Laboratory Report

Report ID: 102889



Sierra
Environmental
Monitoring, Inc.

SPB Utility Services

430 Stoker Avenue, Suite 207

Reno, NV 89503


Date: 12/21/2009
Client: SPB-491
Taken by: K. KANOFF
PO #:

Analysis Report

Sample ID:	Customer Sample ID			Date Sampled	Time Sampled	Date Received	
S200912-1022	Pine View Estates #3200374			12/17/2009	1:30 PM	12/17/2009	
Parameter	Method	Result	Units	MCL	Analyst	Date Analyzed	Data Flag
E. coli P/A	SM 9223 B	ABSENT	P/A	Absent	Kobza	12/17/2009	
Total Coliform P/A	SM 9223 B	ABSENT	P/A	Absent	Kobza	12/17/2009	


SAMPLE WATER AS TESTED ☒ DID ☐ DID NOT MEET DRINKING WATER STANDARDS.

Data Flag Legend:



**FAXED**

ROGER VATES 11/23


**Laboratory Report****Report ID: 102300****Sierra
Environmental
Monitoring, Inc.**


SPB Utility Services

430 Stoker Avenue, Suite 207
Reno, NV 89503Date: 11/19/2009
Client: SPB-491
Taken by: K. KANOFF
PO #:***Analysis Report***

Sample ID:	Customer Sample ID	Date Sampled	Time Sampled	Date Received
S200911-0852	Pine View Estates #3200374 -	11/17/2009	12:30 PM	11/17/2009

Parameter	Method	Result	Units	MCL	Analyst	Date Analyzed	Data Flag
E. coli P/A	SM 9223 B	ABSENT	P/A	Absent	Kobza	11/17/2009	
Total Coliform P/A	SM 9223 B	ABSENT	P/A	Absent	Kobza	11/17/2009	

SAMPLE WATER AS TESTED / DID DID NOT MEET DRINKING WATER STANDARDS.***Data Flag Legend:***



Laboratory Report

Report ID: 101826

Sierra
Environmental
Monitoring, Inc.

SPB Utility Services

430 Stoker Avenue, Suite 207
Reno, NV 89503

Date: 10/29/2009
Client: SPB-491
Taken by: K. KANOFF
PO #:

Analysis Report

Sample ID:	Customer Sample ID	Date Sampled	Time Sampled	Date Received			
S200910-1252	Pine View Estates #3200374-#1 - 277 Walker	10/27/2009	1:15 PM	10/27/2009			
Parameter	Method	Result	Units	MCL	Analyst	Date Analyzed	Data Flag
E. coli P/A	SM 9223 B	ABSENT	P/A	Absent	Kobza	10/27/2009	
Total Coliform P/A	SM 9223 B	ABSENT	P/A	Absent	Kobza	10/27/2009	
SAMPLE WATER AS TESTED <input checked="" type="checkbox"/> DID <input type="checkbox"/> DID NOT MEET DRINKING WATER STANDARDS.							

Sample ID:	Customer Sample ID	Date Sampled	Time Sampled	Date Received			
S200910-1253	Pine View Estates #3200374-#2 - 39 Connerr	10/27/2009	1:15 PM	10/27/2009			
Parameter	Method	Result	Units	MCL	Analyst	Date Analyzed	Data Flag
E. coli P/A	SM 9223 B	ABSENT	P/A	Absent	Kobza	10/27/2009	
Total Coliform P/A	SM 9223 B	ABSENT	P/A	Absent	Kobza	10/27/2009	
SAMPLE WATER AS TESTED <input checked="" type="checkbox"/> DID <input type="checkbox"/> DID NOT MEET DRINKING WATER STANDARDS.							

Sample ID:	Customer Sample ID	Date Sampled	Time Sampled	Date Received			
S200910-1254	Pine View Estates #3200374-#3 - 236 Walker	10/27/2009	1:15 PM	10/27/2009			
Parameter	Method	Result	Units	MCL	Analyst	Date Analyzed	Data Flag
E. coli P/A	SM 9223 B	ABSENT	P/A	Absent	Kobza	10/27/2009	
Total Coliform P/A	SM 9223 B	ABSENT	P/A	Absent	Kobza	10/27/2009	
SAMPLE WATER AS TESTED <input checked="" type="checkbox"/> DID <input type="checkbox"/> DID NOT MEET DRINKING WATER STANDARDS.							

